

# **Quarterly Report for the Glen Water Treatment Plant and Distribution System**

**Operated by the Ontario Clean Water Agency (OCWA)  
under contract to the Township of Essa  
for the period ending June 30th, 2001**

## **Introduction:**

This report is a summary of the last quarter's water quality, published in accordance with Ontario's Drinking Water Protection Regulation. It includes important information regarding the source of your water, analytical test results, and how it compares to standards set by the Province. If you have any questions regarding this report, please contact our Client Services Representative listed in section 3 below.

During this quarter, the Ontario Clean Water Agency (OCWA) conducted more than 250 tests for water quality parameters. Of those tests done at an Accredited laboratory, no samples were found to exceed the Ontario Drinking Water standards as set out in Ontario Regulation 459/00.

During this quarter, 34 turbidity exceedences were reported per Regulation 459/00. These samples are taken continuously monitored inhouse by online equipment and the spikes are believed to be caused from the starting and stopping of pumps and/or air in the sample lines.

## **Compliance With Provincial Regulations:**

OCWA operates your water facility in accordance with provincial regulations. Here is how we do it:

- **Use of Accredited Labs:** Analytical tests to monitor your water quality are conducted by a laboratory audited by the Canadian Association for Environmental Analytical Laboratories (CAEAL) and accredited by the Standards Council of Canada (SCC). Accreditation ensures that the laboratory has acceptable laboratory protocols and test methods in place. It also requires the laboratory to provide evidence and assurances of the proficiency of the analysts performing the test methods.
- **Operation by Licensed Operators:** Your water treatment plant and distribution system is operated and maintained by the OCWA's competent and licensed staff. The mandatory licensing program for operators of drinking water facilities in Ontario is regulated under the Ontario Water Resources Act (OWRA) Regulation 435/93. Licensing means that an individual meets the education and experience requirements and has successfully passed the certificate exam.

## Quarterly Report for Glen Avenue Water Treatment Plant for the period ending September 30th, 2001

- Sampling and Analytical Requirements: OCWA follows a sampling and analysis schedule required by OWRA Regulation 459/00, the Ontario drinking Water Standards. More information on sampling and analysis including results are available in this report and from your municipal office.
- Adherence to Ministry Guidelines and Procedures: To ensure the protection of the public health and operational excellence, the OCWA adheres to the guidelines and procedures developed by the Ministry of Environment and the Ministry of Health.

### System Information:

<b>Facility Name:</b>	Glen Water Treatment Plant	<b>Client Services:</b>	Steve Rohacek
<b>Total Design Capacity</b>	3940m <sup>3</sup> /day	<b>Phone Number</b>	(416) 326-4926
<b>Raw Water Source</b>	Two wells	<b>E-mail Address</b>	srohacek@OCWA.com
<b>Disinfection Method</b>	Sodium Hypochlorite		
<b>Municipal Location</b>	Township of Essa	<b>Operations Manager</b>	Wayne White
<b>Service Area</b>	Village of Thornton	<b>Phone Number</b>	(705)429-2525
<b>Service Population</b>	351	<b>E-mail Address</b>	wwhite@OCWA.com

**Operational Description:** The present Glen Avenue Water System was constructed in the late 1980's to serve portions of the Cunningham Acres subdivision in Essa Township. A groundwater well system comprised of two drilled wells, control building and submersible well pumps, it presently provides potable water to 34 homes. A hypochlorination feed system housed in the control building ensures disinfection. Well water is stored in four 450 litre pressure tanks, and three 325 litre pressure system, the chlorine residual in the potable water is c measured by an on-line analyzer. Up to 523 m<sup>3</sup> per day of potable water is capable of being produced. Flow from the Glen Avenue system is measured by new twin Trident flow meters (one at each well). Although there are two wells available, only one well at a time is permitted to be in production. The Glen Avenue Well and well house were upgraded in 1995 to accommodate an extension to the subdivision. Larger capacity well pumps were installed in the existing wells along with larger pressure tanks and new flow meters. During construction, a large diameter main was installed to insure a fifteen minute retention time prior to the first consumer. As required by the Certificate of Approval, chlorine residual must be maintained at 0.5 mg/L total and distribution system sampling frequency was increased to twice per week.

## Quarterly Report for Glen Avenue Water Treatment Plant for the period ending September 30th, 2001

### Analytical Test Results:

Micro biological Parameters	July	August	September	Quarter Summary	MAC /IMAC
<b>Total Coliform</b>					
counts/100mls					
Number of Samples	23	22	20	65	
Number of Detectable Results	0	0	0	0	
Min / Max	0	0	0	0	0
Exceedences	0	0	0	0	
<b>E. Coliform</b>					
counts/100mls					
Number of Samples	23	22	20	65	
Number of Detectable Results	0	0	0	0	
Min / Max	0	0	0	0	0
Exceedences	0	0	0	0	
<b>Background</b>					
Number of Samples	9	8	8	25	
Number of Detectable Results	8	1	1	10	
Min / Max	0/12	0/1	2	0/2	200
Exceedences	0	0	0	0	
Typical Source of Contamination	Microbial contaminants, such as viruses and bacteria, may come from septic systems, agricultural livestock operations, wildlife, and wastewater treatment plants.				
Comments: There was no exceedences of the MAC/IMAC this quarter.					

**Quarterly Report for Glen Avenue Water Treatment Plant  
for the period ending September 30th, 2001**

<b>Operational Parameters</b>	July	August	September	<b>Quarter summary</b>	<b>MAC/IMAC</b>
<b>Chlorine Residual</b>					
Number of Samples	31	31	30	92	
Number of Detectable Results	31	31	30	92	
Min/Max	0.2/1.62	0.16/1.69	0.1/1.67		0.2-4.0
Exceedences	0	0	0	0	
<b>Turbidity</b>					
Number of Samples	31	31	30	92	
Number of Detectable Results	31	31	30	92	
Min/Max	0.01/>1.0	0.02/>1.0	.01/>1.0		1
Exceedences	10	14	10	34	

Comments: **Turbidity and Chlorine are monitored continuously with online equipment. Operations staff collect grab samples during their plant checks and measure the chlorine and turbidity with pocket instruments as a comparison to the continuous equipment. All turbidity spikes are reported as per O.Reg 459/00.**

<b>Volatile Organic Parameters</b>	July	August	September	<b>Quarter Summary</b>	<b>MAC/IMAC</b>
Typical Source of Contamination	Organic Chemical Contaminants, including synthetic and volatile organic chemicals, that are byproducts of industrial processes and petroleum production, and can also come from gas stations, urban storm water runoff, and septic systems.				
Comments: <b>Volatile organic parameters were tested in july and no exceedences occurred.</b>					

<b>Inorganic Parameters</b>	July	August	September	<b>Quarter Summary</b>	<b>MAC/IMAC</b>
Typical Source of Contamination	Inorganic contaminants, such as salts and metals, can be naturally-occurring or result from urban storm water runoff, industrial, or domestic wastewater discharges, oil & gas production, mining.				
Comments: <b>Inorganics were not tested in this quarter.</b>					

## Quarterly Report for Glen Avenue Water Treatment Plant for the period ending September 30th, 2001

Pesticides and PCB Parameters	July	August	September	Quarter Summary	MAC / IMAC
Typical Source of Contamination	Pesticides and herbicides, may come from a variety of sources such as agriculture, urban storm water runoff, and residential uses.				
Comments: <b>PESTICIDES AND PCB PARAMETERS WERE TESTED IN JULY AND NO EXCEEDENCES OCCURRED.</b>					

Radiological Parameters	July	August	September	Quarter Summary	MAC / IMAC
Typical Source of Contamination	Man made or natural elements emitting radiation in the form of alpha, beta or gamma particles				
Comments: <b>RADIOLOGICAL PARAMETERS WERE NOT TESTED IN THIS QUARTER.</b>					

### **Discussion of Analytical Results:**

During this quarter no microbiological testing exceeded the MAC/IMAC limits. There were many turbidity spikes in this quarter. These spikes were reported as per O.Reg. 459/00. It should be noted that at the times of all the turbidity spikes that the system was receiving adequate disinfection. Turbidity spikes are an ongoing problem and is believed to be equipment related. Spikes can occur from pump cycles as well as air and/or dirt in the sample lines.

### **Availability of Analytical Test Results:**

The certificate of approval from the Ministry of the Environment, and Regulation 459/00 set out monitoring requirements for your water. The tables above summarize all the results required for inclusion in quarterly reports. Your water is extensively tested for the presence of dozens of compounds. Some compounds, not listed above, may be present in low concentrations and their presence does not necessarily mean that the water poses a health risk. Results of all analytical tests are available through your municipal office.

## Quarterly Report for Glen Avenue Water Treatment Plant for the period ending September 30th, 2001

### Definitions and Abbreviations:

- **MAC** - Maximum Acceptable Concentration.
- **IMAC** - Interim Maximum Acceptable Concentration.
- **Coliform Bacteria** - a group of commonly occurring rod shaped bacteria. Their presence in a water sample is indicative of inadequate filtration and/or disinfection.
- **Fecal Coliform Bacteria** - refers to a subgroup of coliform bacteria present in the digestive system of warm blooded animals and humans.
- **Heterotrophic Plate Count** - a method of measuring bacterial content in water samples. Also known as Standard Plate Count.
- **Organic Parameter** - a group of chemical compounds containing carbon.
- **Inorganic Parameter** - a group of chemical compounds not containing carbon.
- **Raw Water** - Surface or ground water available as a source of drinking water that has not received any treatment.